**JAPANESE** 

[JP,2001-277629,A]

CLAIMS DETAILED DESCRIPTION TECHNICAL FIELD PRIOR ART EFFECT OF THE INVENTION TECHNICAL PROBLEM MEANS DESCRIPTION OF DRAWINGS DRAWINGS

[Translation done.]

\* NOTICES \*

JPO and INPIT are not responsible for any

damages caused by the use of this translation.

- 1. This document has been translated by computer. So the translation may not reflect the original precisely.
- 2.\*\*\* shows the word which can not be translated.
- 3.In the drawings, any words are not translated.

## **DESCRIPTION OF DRAWINGS**

[Brief Description of the Drawings]

[Drawing 1] It is a sectional side elevation of a facsimile machine.

[Drawing 2] They are a recording form [ / near the printing unit ], and a course \*\*\*\* side view of an ink sheet.

[Drawing 3] It is a top view of an ink sheet cartridge.

[Drawing 4] It is the perspective view seen from the forward left side of an ink sheet cartridge.

[Drawing 5] It is the perspective view seen from the forward right side of an ink sheet cartridge.


[Drawing 6] It is a right side view of an ink sheet cartridge.

[Drawing 7] It is a left side view of an ink sheet cartridge.

[Drawing 8] It is an exploded perspective view in the state where the parts of the ink sheet cartridge turned over.

[Drawing 9] They are the 1st rotating member 46, the collar-head shank 48, and an exploded perspective view of

Drawing selection Representative draw



[Translation done.]

intermediate adapter 70 grade.

[Drawing 10] As for the front view of the 1st rotating member 46, and (b), the left side view of drawing 10 (a) and (d of the Xb-Xb line arrowed cross-section figure of drawing 10 (a) and (c)) are [ (a) ] the right side views of drawing 10 (a).

[Drawing 11] As for the front view of the collar-head shank 48, and (b), the XIb -XIb line arrowed cross-section figure of drawing 11 (a) and (c) of (a) are the right side views of drawing 11 (a).

[Drawing 12](a) is a right-hand side perspective view of the collar-head shank 48, and, similarly (b) is a left-hand side perspective view.

[Drawing 13](a) is a partial notch front view of an intermediate adapter, and a part of (b) is a notch right side view.

[Drawing 14] It is an expanded sectional view showing the connecting position relation between the 1st rotating member 46, the collar-head shank 48, and the intermediate adapter 70.

[Drawing 15] It is an expanded sectional view showing a connecting state.

[Description of Notations]

20 Ink sheet cartridge

- 21 Ink sheet
- 24 Diaphragm
- 25 Supply side sheet spool
- 26 Rolling-up side sheet spool
- 30 Cartridge body
- 31a and 31b Side plate
- 32 The piece of an arm top cover
- 36-39 Spool
- 40 and 41 Core tube
- 42 Internal cylinder part
- 43, 48a flange
- 45 Gear part
- 46 The 1st rotating member
- 47 Transmission-tooth vehicle
- 48 Shank
- 48b Base
- 50 Boss
- 51 Elastic body
- 51a Locking claw
- 52 Engaging body
- 52a Tip claw part

[Translation done.]

Scarcii Result
53 Fitting hole
53a Step
54 Locating lug
55 Tooling holes
60 Notch groove
70 Intermediate adapter
70a Cylinder part
70b Flange
71 Locking hole
72 The 1st engaging projection
73 The 2nd engaging projection